Manual to create recovery USB Stick:

For creating a recovery usb drive the following steps need to be followed:

Files needed:
- OPSW10_21H1.bin
- imageusb.zip

ImageUSB can be foud at:

https://www.osforensics.com/tools/write-usb-images.html

For verification, the MD5 hash of OPSW10_21H1.bin:

14615F24553CD0BB8C0264EFB8389904

Plug in the USB stick and start ImageUSB application

Select the USB stick:

Make sure that Write Image to USB drive is selected:

Select the downloaded image file: OPSW10_21H1.bin

Press Write:

After write is complete, boot the OPS module from the USB stick.