



## Release Notes – Prowise Central v7.2

AOSP	EDLA	Windows
PWT (Gen 1, 2)	TS Ten (Gen 4)	TS Max
TS One (Gen 1, 2)		
TS Ten (Gen 1, 2, 3, 3 SE)		
TS Ultra		

### 1.0 Release schedule

- Internal release → 05-05-2026
- Partner release → 11-05-2026
- Limited release → 01-06-2026 (Android limited, Windows full)
- Full release → 08-06-2026

### 1.1 General info and screen type support

In this release we provide an update to the existing Prowise Central solution for our Central enabled Touchscreens. For the following screen types and numbers the update will be made available as an “Over-the-Air”-image (OTA) update:

AOSP	55"	65"	75"	86"	98"
<b>PWT G1</b> (einstein) fw: 2.2.79 build: 202604231150	PW.1.15055.1001	PW.1.15065.0001	PW.1.15075.0001	PW.1.15086.0001	-
<b>PWT G2</b> (einstein) fw: 2.2.79 build: 202604231150	-	PW.1.15065.1001	PW.1.15075.1001	PW.1.15086.1001	-
<b>One G1</b> (hermes) fw: 1.1.2 build: 202604231154	-	PW.1.16065.0001	PW.1.16075.0001	PW.1.16086.0001	-



AOSP	55"	65"	75"	86"	98"
<b>One G2</b> (volta) fw: 1.1.39 build: 20260430193218	-	PW.1.16065.0002	PW.1.16075.0002	PW.1.16086.0002 PW.1.16086.0002M	PW.1.16098.0002
<b>Ten G1</b> (eisler) fw: 1.0.43 build: 202604231452	PW.1.17055.0001	PW.1.17065.****	PW.1.17075.****	PW.1.17086.****	PW.1.17098.1001
<b>Ten G2</b> (kepler) fw: 1.1.39 build: 20260430172721	-	PW.1.17065.0002	PW.1.17075.0002	PW.1.17086.0002	-
<b>Ten G3</b> (odin) fw: 1.0.32 build: 20260430130041	-	PW.1.17065.0003	PW.1.17075.0003	PW.1.17086.0003	PW.1.17098.0003
<b>Ten G3 SE</b> (odin light) fw: 1.0.4 build: 20260430213241	-	PW.1.17065.0003	PW.1.17075.0003	PW.1.17086.0003	PW.1.17098.0003
<b>Ultra</b> (wodan) fw: 1.0.32 build: 20260430151211	PW.1.18055.0001	PW.1.18065.0001	PW.1.18075.0001	PW.1.18086.0001	-

EDLA	55"	65"	75"	86"	98"
<b>Ten G4</b> (mercury) fw: 1.0.416 build: 20260430144431	-	PW.1.17065.0004	PW.1.17075.0004	PW.1.17086.0004	PW.1.17098.0004

Windows	65"	75"	86"	98"
<b>TS Max</b> (athena) fw: 7.2.0	PW.1.19065.0001	PW.1.19075.0001	PW.1.19086.0001	PW.1.19098.0001.

Windows	92"	105"
TS Max (thor) fw: 7.2.0	PW.1.19092.0001	PW.1.19105.0001

## 1.2 New features

Feature	Description	Touchscreen Type
Prowise Reflect phased out	Prowise Reflect as a streaming protocol is disabled and will not be continued	AOSP, EDLA
Prowise Appstore	Support for xapk file format; with which we can support a broader variety of Android apps	AOSP
Filemanager WebDAV support	Support for WebDAV cloud integrations	AOSP
Network details	Ability to set static LAN settings and updated WiFi and LAN views; e.g. when an ethernet cable is connected / disconnected	AOSP, EDLA
Android version visibility	The Android version is now visible in the "About" section	AOSP, EDLA
Lift collision detection sound	When a collision is detected a sound will be played as well	AOSP, EDLA
Advanced settings design	Re-designed advanced settings according to the latest Prowise styling guidelines	AOSP, EDLA
Teach as ProNote replacement	On the TS Ten G1 ProNote has been replaced by Teach	AOSP (TS Ten Gen 1)
Screen control support	Prowise Screen Control support including official Google MDM enrollment	EDLA
Statistics (Screen Control)	Information about app usages and storage usages can now be seen in the Screen Control device overview	AOSP, EDLA

Feature	Description	Touchscreen Type
---------	-------------	------------------

Prowise Screen Control support	Ability to enroll a TS Max Windows based touchscreen in Prowise Screen Control	Windows
NFC login	Ability to login to Windows using a Prowise NFC card	Windows
Configure bezel buttons	Ability to configure the bottom bezel buttons; ability to select input channels as quick actions	Windows
Remote control	Ability to enable/disable the remote control	Windows
Minitools	The minitools can now be opened nearby the Hybrid Menu	Windows
Customize desktop widgets	Ability to select which items are shown on the desktop	Windows
Streaming protocols	Streaming protocols have been optimized (AirPlay, Chromecast, Miracast) → ability to close sessions on the screen itself	Windows
Camera settings	The camera settings have been moved from the Hybrid Menu to the settings	Windows

### 1.3 Solved high priority bugs

Bug	Description	Touchscreen Type
OTA update fails	Checking for manual updates did not work correctly all the time	AOSP
AirPlay connection issues	AirPlay connection flows are improved (dependent on specific iOS versions)	AOSP, EDLA
Screenshot issues	Screenshot appeared to be black sometimes (TS Ten Gen 2, TS One Gen 2)	AOSP
Live preview input app	Not able to see any input when connecting to HDMI (TS Ten Gen 3). When input channels are disabled, these will not be shown in the Live preview app	AOSP, EDLA
Status online / offline screen control	Devices seem to be offline after a certain period	AOSP, EDLA

Top region not able to touch	Near the region where the device name is displayed, touch was not possible	AOSP, EDLA
------------------------------	--	------------

Bug	Description	Touchscreen Type
"White blocks" issue	Resolved the "white blocks" issues which were visible sometimes	Windows
Clock widget	The clock widget disappeared sometimes when a wallpaper was changed	Windows
Missing audio output input channel	In some cases audio was not hearable when connecting an external input channel	Windows
Automatic pen pickup trigger from proximity sensor	Sometime a pen pickup would trigger when a presence was detected	Windows

#### 1.4 Known issues / Missing features

AOSP Issue	Description/workaround
Desktop; Non-working widgets	Some of the apps available from the Prowise app store have widgets which seem to be non-working. Non-working widgets will be removed in next Prowise Central releases
Prowise Browser; Not able to make a weblink easily	The "Add to home" button does not function when tapping it in the middle. Workaround is to tap slightly in the bottom right or using the three dot menu (TS Ten G1 only)
IP232; Not possible to send a P_On command, all other commands work (TS Ten)	Send WOL command to wake up the screen from standby
Switching Move camera between Central and Windows	From Move to Windows works fine. Back from Windows to the Move app, does not automatically pick up the live camera feed. Move app needs to be restarted.
ProNote	Stopwatch seems frozen when it's running and user starts drawing (TS One, PWT)
Prowise Browser	TS One Gen 1; when performing a factory reset on Central v7.2, the Prowise Browser will not be installed by default anymore. The app can be downloaded from the appstore.

## 1.5 Re-cap streaming protocols

AirPlay / Chromecast	<ul style="list-style-type: none"><li>- Stream 30 devices simultaneously (audio + video)</li><li>- Mixed content (so for example 5 iOS devices and 5 chromecast devices at the same time)</li><li>- Mac and Windows clients have touch support</li><li>- Waiting list mode (not available for the PWT)</li></ul>
Miracast	<ul style="list-style-type: none"><li>- Stream 1 device (audio + video)</li><li>- TS Max has mixed streaming protocol support</li></ul>
Presenter 10 (n/a on the TS One Gen 1)	<ul style="list-style-type: none"><li>- Connect multiple devices simultaneously</li><li>- Connect tablets, smartphones and other devices with the touchscreen to easily collect input from the class.</li><li>- Support for Windows, Mac, IOS, Android, Chrome OS and Linux devices</li></ul>

## 1.6 Update procedure

Press the "Check for system updates" button in the "Settings" menu under "About this screen". When an update is found you can press OK to start the update, the screen will automatically reboot or shutdown when ready (depending on the screen type).